

Model: SAMSUNG MZ7LM1T9

S/N:

Disk Erasure Report

Page 1 - Erasure Status



Organisation Performing The Disk Erasure

Business Name: **GridJet**

Business Address:

Contact Name: **GDW-LDS-6**

Contact Phone:

Customer Details

Name: **Gridjet**

Address:

Contact Name:

Contact Phone:

Disk Information

Make/Model: **SAMSUNG MZ7LM1T9**

Serial: **Unknown**

Size(Apparent): **1006 MB, 0 bytes**

Bus: **UNK**

Size(Real): **1006 MB, 1006260736 bytes**

Disk Erasure Details

Start time: **1970/01/01 01:00:00**

End time: **1970/01/01 01:00:00**

Duration: **00:00:00**

Status: **INSANITY**

Method: **PRNG Stream**

PRNG algorithm: **XORshiro256**

Final Pass(Zeros/Ones/None): **Zeros**

Verify Pass(Last/All/None): **Verify Last**

*Bytes Erased: **0, (0.00%)**

Rounds(completed/requested): **-1/1**

HPA/DCO: **Hidden sectors found!**

HPA/DCO Size: **1 sectors**

Errors(pass/sync/verify): **0/0/0**

Throughput: **0 B/sec**


Information:

* bytes erased: The amount of drive that's been erased at least once

Technician/Operator ID

Signature:

Name/ID: **Auto Wipe**



Model: SAMSUNG MZ7LM1T9

S/N: Unknown

Disk Erasure Report

Page 2 - Smart Data



smartctl 7.2 2020-12-30 r5155 [x86_64-linux-5.14.0-503.23.1.el9_5.x86_64] (local build)
copyright (c) 2002-20, bruce allen, christian franke, www.smartmontools.org

smartctl open device: /dev/sdkv failed: INQUIRY failed