



Model: TOSHIBA MK3001GRRB

S/N: 32F0A0P6FQ85

Disk Erasure Report

Page 1 - Erasure Status



Organisation Performing The Disk Erasure

Business Name: **GridJet**

Business Address:

Contact Name: **GDW-LDS-6**

Contact Phone:

Customer Details

Name: **Gridjet**

Address:

Contact Name:

Contact Phone:

Disk Information

Make/Model: **TOSHIBA MK3001GRRB**

Serial: **32F0A0P6FQ85**

Size(Apparent): **300 GB, 300000000000 bytes**

Bus: **SAS**

Size(Real): **300 GB, 300000000000 bytes**

Disk Erasure Details

Start time: **2025/02/12 12:15:29**

End time: **2025/02/12 14:19:30**

Duration: **02:04:01**

Status: **ERASED** **See Warning !**

Method: **PRNG Stream**

PRNG algorithm: **XORshiro256**

Final Pass(Zeros/Ones/None): **Zeros**

Verify Pass(Last/All/None): **Verify Last**

*Bytes Erased: **300000000000, (100.00%)**

Rounds(completed/requested): **1/1**

HPA/DCO: **Unknown**

HPA/DCO Size: **Unknown**

Errors(pass/sync/verify): **0/0/0**

Throughput: **120 MB/sec**

Information: **Warning** **HPA/DCO data unavailable, can not determine hidden sector status.**

* bytes erased: The amount of drive that's been erased at least once

Technician/Operator ID

Signature:

Name/ID: **Auto Wipe**



Model: TOSHIBA MK3001GRRB
S/N: 32F0A0P6FQ85



Disk Erasure Report

Page 2 - Smart Data

smartctl 7.2 2020-12-30 r5155 [x86_64-linux-5.14.0-503.23.1.el9_5.x86_64] (local build)
copyright (c) 2002-20, bruce allen, christian franke, www.smartmontools.org

=== start of information section ===

vendor: TOSHIBA
product: MK3001GRRB
revision: DB02
compliance: SPC-4
user capacity: 300,000,000,000 bytes [300 GB]
logical block size: 512 bytes
rotation rate: 15000 rpm
form factor: 2.5 inches
logical unit id: 0x50000393e8197c94
serial number: 32F0A0P6FQ85
device type: disk
transport protocol: SAS (SPL-3)
local time is: Wed Feb 12 14:19:32 2025 GMT
smart support is: Available - device has SMART capability.
smart support is: Enabled
temperature warning: Disabled or Not Supported

=== start of read smart data section ===

smart health status: OK

current drive temperature: 32 C
drive trip temperature: 65 C

accumulated power on time, hours:minutes 110638:47
manufactured in week 11 of year 2012
specified cycle count over device lifetime: 50000
accumulated start-stop cycles: 9
specified load-unload count over device lifetime: 200000
accumulated load-unload cycles: 0
elements in grown defect list: 0

error counter log:

	errors corrected by		total	correction	gigabytes	total
	ecc		errors	algorithm	processed	uncorrected
	fast	delayed	rewrites	invocations	[10^9 bytes]	errors
read:	0	171065	171065	249730	1248092.544	0
write:	0	281	282	1746	197334.777	1
verify:	0	15499	15499	16289	197707.798	0

non-medium error count: 6

smart self-test log

num	test description	status	segment number	lifetime (hours)	lba_first_err	[sk asc asq]
# 1	background short	completed	32	65535	-	[- - -]
# 2	background short	completed	32	65535	-	[- - -]
# 3	background short	completed	32	65535	-	[- - -]
# 4	background short	completed	32	65535	-	[- - -]
# 5	background short	completed	32	65535	-	[- - -]
# 6	background short	completed	32	65535	-	[- - -]
# 7	background short	completed	32	65535	-	[- - -]
# 8	background short	completed	32	65535	-	[- - -]
# 9	background short	completed	32	65535	-	[- - -]
#10	background short	completed	32	65535	-	[- - -]
#11	background short	completed	32	65535	-	[- - -]
#12	background short	completed	32	65535	-	[- - -]
#13	background short	completed	32	65535	-	[- - -]
#14	background short	completed	32	65535	-	[- - -]
#15	background short	completed	32	65535	-	[- - -]
#16	background short	completed	32	65535	-	[- - -]



Model: TOSHIBA MK3001GRRB
S/N: 32F0A0P6FQ85

Disk Erasure Report

Page 3 - Smart Data



#17	background short	completed	32	65535	-	[-	-	-]
#18	background short	completed	32	65535	-	[-	-	-]
#19	background short	completed	32	65535	-	[-	-	-]
#20	background short	completed	32	65535	-	[-	-	-]

long (extended) self-test duration: 1725 seconds [28.8 minutes]